

**Issued to:**  
 RAPID EPS  
 UNIT D  
 TREEFIELD IND EST  
 GELDERD ROAD  
 GILDERSOME  
 LEEDS  
 LS27 7JU

**Location of equipment:**  
 RAPID EPS  
 UNIT D  
 TREEFIELD IND EST  
 GELDERD ROAD  
 GILDERSOME  
 LEEDS  
 LS27 7JU

**Issued by:**  
 Lloyds British a division of  
 Speedy Asset Services Ltd  
 Brunel Industrial Estate  
 Blyth Road  
 Harworth  
 DN11 8QA  
 Tel: 01302 751267



<b>Report no:</b>	PRJ033783/C
<b>Your Order no:</b>	18323
<b>Our Job no:</b>	PRJ033783
<b>Sheet no:</b>	1 of 1

## ***Report of Test and Thorough Examination of Lifting Plant and Equipment***

*This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998, SI 2307*

Identification Mark of the Equipment:	Description of Equipment	Details of Test and Thorough Examination				
		Qty Tested and Examined:	Safe Working Load: (Specify Units)	Proof Load Applied: (Specify Units)	Additional/Examination/Standards	Date of Test and Examination:
BATCH TEST 3	SINGLE DUAL PURPOSE STAND 3.2 MTR HEIGHT CODE AU007B 50MM X 50MM SHS TRIPLE HEIGHT STAND SCREWED TO CLT TEST BASE USING 3 NUMBER 8MM X 60MM HECO TOPIX SCREWS	1	N/A	130 KN	<b>STANDARD</b> AUSTRALIA & NEW ZEALAND AS/NZ 4994.1:2009 LOAD APPLIED @ 1.2 METRE HEIGHT ONLY RESULT: 26MM DEFLECTION NO SCREW MOVEMENT NO DEFORMATION	15/10/19

***The above equipment has been thoroughly examined, no defects found and is safe to operate***



**Name and address of person authenticating and signing this report on behalf of author:**

**Name:** NEIL JOHNSTON

**Position:** TEST ENGINEER

**Signature:** 

**Date of Report:** 22<sup>ND</sup> October 2019

