

Issued to:
 RAPID EPS
 UNIT D
 TREEFIELD IND EST
 GELDERD ROAD
 GILDERSOME
 LEEDS
 LS27 7JU

Location of equipment:
 RAPID EPS
 UNIT D
 TREEFIELD IND EST
 GELDERD ROAD
 GILDERSOME
 LEEDS
 LS27 7JU

Issued by:
 Lloyds British a division of
 Speedy Asset Services Ltd
 Brunel Industrial Estate
 Blyth Road
 Harworth
 DN11 8QA
 Tel: 01302 751267



Report no:	PRJ030198/003B
Your Order no:	
Our Job no:	PRJ030198-B
Sheet no:	1 of 1

Report of Test and Thorough Examination of Lifting Plant and Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998, SI 2307

Identification Mark of the Equipment:	Description of Equipment	Details of Test and Thorough Examination				
		Qty Tested and Examined:	Safe Working Load: (Specify Units)	Proof Load Applied: (Specify Units)	Additional/Examination/Standards	Date of Test and Examination:
TEST 1A	TEST OF 3.2M DUAL PURPOSE STAND WITH M8 X 60MM HECO TOPIX RAPID EPS DUAL PURPOSE STAND TRIPLE HEIGHT CODE NUMBER AU007B AFFIXED TO TOP FACE OF CROSS LAMINATED TIMBER USING 3 NUMBER M8 X 60MM HECO TOPIX FIXINGS	1		130 KG	REPORT OF LOAD TEST LOAD APPLIED AT 1MTR HEIGHT DEFLECTION RECORDED AT 18MM NO PERMANENT DEFORMATION – RETURNED TO WITHIN 1MM POST LOADED TO 130KG NO FAILURE STANDARD AUSTRALIA & NEW ZEALAND AS/NZ 4994.1 2009	23/09/19

The above equipment has been thoroughly examined, no defects found and is safe to operate



Name and address of person authenticating and signing this report on behalf of author:

Name: Neil Johnston

Position: TEST ENGINEER

Signature: 

Date of Report: 23 September 19

